Firmware Update to 150708_B1_01_03

Unzip NST-370A31_B10103.zip and Run MPTool.exe

Unlock password: asmedia

Firmware Update to 150708_B1_01_03

FW Browse and select firmware file 150708_B1_01_03.bin

Make sure the correct firmware is loaded and Update FW / Reload FW is selected

Firmware Update to 150708_B1_01_03

Click start to run the update until progress bar 100% and PASS is displaying on the screen
Now the enclosure firmware version is updated to 150708_B1_01_03