




- 1) Unzip JMS539_v255.0.3.42.22
- 2) Power on the HX4 and connect to an USB port
- 3) Run FwUpdateTool_v1_18_01.exe and make sure JMS551/539 chip has been selected



- 4) Load File and select firmware file ES-51-197G-4222(JMS539_PM_255.0.3.42.22_20100928).bin



5) Run to perform firmware update



6) Now you can power cycle the enclosure to complete firmware update

